

Presbyterian Parsonage
Oxford, Ohio.

HABS No. O-622 ✓

HABS
OHIO
9-OXFO
2-

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA
District of Cincinnati, Ohio

Historic American Buildings Survey
In Collaboration with Architectural Department, Miami University
Charles R. Strong, District Officer
3700 Carew Tower, Cincinnati, Ohio

PRESBYTERIAN PARSONAGE
Oxford, Butler County, Ohio

Owner. Presbyterian Church, Oxford, Ohio.

Date of Erection. Early 1850's.

Builder. S. R. Molyneaux.

Present Condition. In fine state. Dormer window added recently. Present garage was dining room. Present laundry was kitchen. Coal cellar was fruit and vegetable storage room. West side of first floor had three bedrooms of equal size. Middle room changed to bath-room and closet. On east side, front room was sitting room; middle room was study; back room was bed-room. Now front room is bed-room, middle room is dining room, and back room is kitchen.

Number of Stories. One and one-half.

Materials of Construction. Stone foundation, brick walls, wood shingle roof.

Other Existing Records. None except incidental data in hands of present occupants.

Additional Data. Lot on which house is built originally ran from High Street to Church Street. A. K. Morris bought back part of lot in 1921.

Compiled by-

Approved by-

Charles R. Strong
District Officer.

1/7/32 - MW.